



KAUS VANS BV

Mercedes-Benz Sprinter 319 CDI V6 3.0 L Injektor problem

General features

Brand	Mercedes-Benz
Subcategory	Drop side
Odometer reading	205.038km
Date of first registration	12-12-2012
Color	White
Condition	Used
General condition	Good
Fuel	Diesel
Emission class	Euro 5



Characteristics

Empty weight	2.417kg
Load capacity	1.083kg
GVW	3.500kg
Length	340cm
Width	205cm
Cabin	cabin.
Door count	4
Cylinder contents	2.987cc

Mercedes-Benz Sprinter 319 CDI V6 3.0 L Injektor problem

Technical specifications

Transmission	Manual
--------------	--------

Engine output	190hp
---------------	-------

Description

Mercedes Sprinter 319 CDI V6 3.0. Bouwjaar 10-12-2012. Voertuig heeft een sterke 190 pk v6 motor. Waarschijnlijk is er een injektor kapot want hij rookt erg en ruikt naar diesel. Motor draait gewoon goed en heeft alle vermogen. Is voorzien van airco en nog aantal optie's.

Accessories

- Onboard Computer
- ESP
- Rain Sensor
- Anti-lock braking system
- Air conditioning
- Leaf spring suspension
- Central locking
- Electrically operated windows
- Parabolic suspension
- Radio/CD player
- Particulate filter
- Visor
- Catalyst
- Trailer coupling
- Power steering
- Passenger seat
- Radio/Cd/Audio system
- Electric windows
- Climate control
- ASR (Anti-Slip Regulation/Traction Control)