



KAUS VANS BV

Volkswagen Crafter 2.0 TDI L2 H2 180 PK Injector Problem

General features

Brand	Volkswagen
Model	Crafter
Subcategory	Closed
Licence plate	v01lzd
Odometer reading	140.943km
Construction year	2020
Date of first registration	06-02-2020
Color	White
Condition	Used
General condition	Good
Fuel	Diesel
Emission class	Euro 6



Characteristics

Empty weight	1.998kg
Load capacity	1.502kg
GVW	3.500kg
Length	599cm
Width	204cm
Door count	5
Cylinder contents	1.968cc

Volkswagen Crafter 2.0 TDI L2 H2 180 PK Injector Problem

Technical specifications

Number of axes	2
Axis configuration	4x2
Transmission	Manual
Engine output	180hp

Description

Volkswagen Crafter 2.0 TDI L2 H2. Bouwjaar 06-02-2020. Voertuig is voorzien van Airco, Navigatie, Cruisecontrol, Achteruitrijcamera, Parkeersensoren, Trekhaak enz !! Euro 6 motor met 180 PK en 140.943 KM. Injector probleem !!

Accessories

- Apple CarPlay
- Bluetooth
- ESP
- Heated Mirrors
- Towbar
- Anti-lock braking system
- Reversing camera
- Air conditioning
- Central locking
- Cruise control
- Electrically operated windows
- Navigation system
- Spare wheel
- Particulate filter
- Side door
- Catalyst
- Parkassist
- Trailer coupling
- Power steering
- Passenger seat
- Airbags
- Central doorlocking
- Electric windows
- EBS
- Heater
- Alarm
- ASR (Anti-Slip Regulation/Traction Control)