



KAUS VANS BV

Mercedes-Benz Sprinter 319 CDI V6 3.0 L Injektor problem

Общие характеристики

Бренд	Mercedes-Benz
Подкатегория	откидной борт
Пробег	205.038km
firstRegistrationDate	12-12-2012
Цвет	остроумие
Состояние	Использовано
Общее состояние	Хороший
energyType	energyType.diesel
Класс эмиссии	Euro 5



Свойства

Снаряжённая масса	2.417kg
payloadWeight	1.083kg
GVW	3.500kg
length	340cm
width	205cm
cabin	cabin.
doorCount	4
engineDisplacement	2.987cc

Mercedes-Benz Sprinter 319 CDI V6 3.0 L Injektor problem

Технические характеристики

Трансмиссия

power

Руководство

190hp

Описание

Mercedes Sprinter 319 CDI V6 3.0. Bouwjaar 10-12-2012. Voertuig heeft een sterke 190 pk v6 motor. Waarschijnlijk is er een injektor kapot want hij rookt erg en ruikt naar diesel. Motor draait gewoon goed en heeft alle vermogen. Is voorzien van airco en nog aantal optie's.

accessories

- Onboard Computer
- ESP
- Rain Sensor
- Anti-lock braking system
- Air conditioning
- Leaf spring suspension
- Central locking
- Electrically operated windows
- Parabolic suspension
- Radio/CD player
- Particulate filter
- Visor
- Catalyst
- Trailer coupling
- Power steering
- Passenger seat
- Radio/Cd/Audio system
- Electric windows
- Climate control
- ASR (Anti-Slip Regulation/Traction Control)